URGENT MEDICAL DEVICE - REMOVAL

FSCA 2242352-09/20/2024-002-R

VasoView HemoPro Endoscopic Vessel Harvesting Systems VH-3000-W & VH-3500

| Product Name | VasoView HemoPro Endoscopic Vessel Harvesting System | | | | |
|----------------------------------|---|----------------|--|--|--|
| Product Code | VH-3000-W / VH-3500 | | | | |
| UDI-DI | VH-3000-W | 00607567700413 | | | |
| | VH-3500 | 00607567701250 | | | |
| Distributed Affected Lot Number: | See the attached listing (Page 4) for all applicable lot numbers. | | | | |
| Manufacturing Dates for All: | September 08, 2023, to July 26, 2024 | | | | |
| Distribution Dates for All: | September 25, 2023, to July 19, 2024 | | | | |

Dear Risk Manager,

Maquet Cardiovascular, LLC (MCV), a subsidiary of Getinge, is initiating a voluntary Medical Device Removal for all affected products within its shelf life of the VasoView HemoPro Endoscopic Vessel Harvesting (EVH) Systems due to complaints received of silicone detaching from the Harvesting Tool component of the device during use, resulting in debris being introduced to affected patients.

The VasoView HemoPro EVH Systems (product codes VH-3000-W (outside the U.S.) and VH-3500) are indicated for use in minimally invasive surgery allowing access for vessel harvesting and are primarily indicated for patients undergoing endoscopic surgery for arterial bypass. The Harvesting Cannula has four lumens that house the Endoscope, C-Ring, distal lens washer tube, and VasoView HemoPro Harvesting Tool. The Harvesting Tool is used for cutting and cauterizing vessel branches and has two curved Jaws. One of the Jaws contains the heating elements for branch cutting and cauterizing. Both Jaws have silicone insulation to protect the adjacent tissue.

Identification of the issue:



MCV/Getinge received 18 complaints for the VH-3500 devices between 01-Apr-2024 and 31-July-2024 related to silicone detaching from the Jaws of the Harvesting Tool during use. There were 17 reports of serious injury due to silicone debris being introduced to the patients including 3 instances where this debris was unable to be removed. MCV/Getinge has determined that this issue potentially impacts all manufactured lots of the VH-3000-W and VH-3500 devices and is, therefore, removing all affected product within its shelf life from the field.

Risk To Health:

Detachment of silicone from the Hemopro Harvesting Tool Jaws can render the device Harvesting Tool non-functional, requiring replacement. If silicone detaches into the endoscopic tunnel while the device is in use, detached material must be removed from the patient. This hazardous situation can lead to an EVH procedural delay and/or conversion of the EVH procedure to a more invasive open vessel harvest (OVH) procedure. Conversion to an OVH procedure may increase a patient's risk of pain, bleeding, delayed wound healing, infection, a longer hospitalization, and potentially a longer recovery due to the increased number or length of incision required by the procedure.

Additionally, there is a risk that the detached silicone may be too small to be removed endoscopically or could go unnoticed by the surgical team and be retained within the endoscopic tunnel, and potentially lead to future complications and harm to the patient. Future complications could include such harms as delayed onset of pain, infection, localized allergic/adverse reaction, and/or readmission to a medical facility for additional medical and/or surgical intervention to treat complications and/or retrieve retained material.

Actions to be taken by the customer:

Our records indicate that you have received one or more of the VasoView HemoPro EVH Systems that are affected by this notification.

- Please forward this information to all current and potential VasoView HemoPro Endoscopic Vessel Harvesting System users within your hospital/facility.
- 2. If you are a distributor who has shipped any affected products to customers, please forward this document to their attention for appropriate action.
- 3. Please examine your inventory immediately to determine if you have any of the VasoView HemoPro EVH Systems with the product codes and lot numbers listed in this notice and remove these from use.
- 4. Return any unused/unexpired affected product to MCV/Getinge. Please contact MCV/Getinge Customer Service at 1-888-880-2874 between the hours of 6:00 am and 5:00 pm PST (Pacific Standard Time) to request a return authorization



number (RMA) and shipping instructions. If you have an affected product, you are entitled to a credit. You will receive credit upon your acknowledgment that you have affected the product for return.

5. Whether or not you have affected the product, please complete, and sign the attached MEDICAL DEVICE REMOVAL - RESPONSE FORM (page 5) to acknowledge that you have received this notification. Return the completed form to MCV/Getinge by emailing a scanned copy to Hemopro-peeling-detached-silicone2024.act@getinge.com or by faxing the form to +1 (866) 594 8101.

Actions to be taken by Getinge:

MCV/Getinge is continuing to investigate this issue to determine and implement the appropriate actions to prevent the recurrence of this failure. MCV/Getinge will notify customers in the event additional action is needed to address this issue.

Getinge will facilitate the removal of affected products from your facility and provide credit for your return of these products. This voluntary removal only affects the products listed on page 1; no other products are affected by this voluntary medical device removal.

Adverse reactions or quality problems experienced with the use of this product can be reported to the FDA's MedWatch Adverse Event Reporting program either online, by regular mail or by fax using the following:

- Online: www.accessdata.fda.gov/scripts/medwatch/
- **Regular Mail**: Download form at www.fda.gov/MedWatch/getforms.htm or call 1-800-332-1088 to request a reporting form, then complete and return to the address on the pre-addressed form.
- **Fax**: 1-800-FDA-0178 (1-800-332-0178)

We apologize for any inconvenience this medical device removal may cause. If you have any questions, please contact your MCV/Getinge representative or call the MCV/Getinge Customer Support at 1-888-880-2874, Monday through Friday, between the hours of 6:00 am and 5:00 pm PST.

This notification is being made with the knowledge of the U.S. Food and Drug Administration.

Sincerely,

Sajjad A Mansoor

Director, Quality and Regulatory Compliance



FSCA 2242352-09/20/2024-002-R VasoView HemoPro Endoscopic Vessel Harvesting System

Listing of Affected Batches

VH-3000-W

3000365379 3000382334 3000392749

VH-3500

| <u>v п-3500</u> | | | | | |
|-----------------|------------|------------|------------|------------|------------|
| 3000333967 | 3000354228 | 3000364520 | 3000376542 | 3000384902 | 3000400713 |
| 3000339701 | 3000355224 | 3000365391 | 3000376883 | 3000385174 | 3000401094 |
| 3000340534 | 3000355369 | 3000366446 | 3000377320 | 3000385849 | 3000401623 |
| 3000341133 | 3000355798 | 3000366831 | 3000377699 | 3000386206 | 3000402378 |
| 3000341675 | 3000356048 | 3000367160 | 3000378079 | 3000386871 | 3000403161 |
| 3000342250 | 3000357837 | 3000367439 | 3000378654 | 3000387986 | 3000403837 |
| 3000342251 | 3000360574 | 3000367542 | 3000379282 | 3000387987 | 3000404029 |
| 3000343264 | 3000360576 | 3000367852 | 3000379691 | 3000388401 | 3000404374 |
| 3000343266 | 3000360775 | 3000368165 | 3000380264 | 3000388676 | 3000404720 |
| 3000344887 | 3000361036 | 3000368658 | 3000380475 | 3000389329 | 3000411951 |
| 3000345068 | 3000361423 | 3000369005 | 3000380671 | 3000392530 | |
| 3000346640 | 3000361707 | 3000369122 | 3000381049 | 3000392531 | |
| 3000351187 | 3000362064 | 3000369645 | 3000381287 | 3000393159 | |
| 3000351376 | 3000362258 | 3000370069 | 3000381620 | 3000393427 | |
| 3000351407 | 3000362671 | 3000370290 | 3000382054 | 3000393838 | |
| 3000351619 | 3000362933 | 3000372257 | 3000382868 | 3000394234 | |
| 3000351747 | 3000363162 | 3000375534 | 3000383367 | 3000395128 | |
| 3000351860 | 3000363947 | 3000375776 | 3000383779 | 3000398856 | |
| 3000352770 | 3000364082 | 3000376132 | 3000384088 | 3000399341 | |
| 3000354226 | 3000364309 | 3000376388 | 3000384382 | 3000399911 | |